

Use warnings for CO₂ portable probes



Use warnings for CO₂ measuring probes:

- Do not let the probe exposed to high concentrations (>5000 ppm) for a long period.
- Do not directly blow on the probe.
- After an exposure with high concentration, wait a few minutes, until the device displays a stable measurement.
- During the first 30 seconds of use, the instrument does not make any measurement; this is the time required for warming-up of measuring chamber.



Device shall be adjusted regularly. We recommend a yearly adjustment and calibration.

■ CO₂ / temperature probe – SCO2T



■ CO₂ / temp./hygro. probe – SCO2TH



www.kimo.fr

EXPORT DEPARTMENT
Boulevard de Beaubourg - Emerainville - BP 48
77312 MARNE LA VALLEE CEDEX 2
Tel : + 33.1.60.06.69.25 - Fax : + 33.1.60.06.69.29